

THE MERCEDES-BENZ SERVICE PACKAGES



MODEL	MINOR (FROM 8,000KMS) KSHS	MAJOR (FROM 30,000KMS) KSHS
A-CLASS	12,000	26,000
C-CLASS		
W203 111 Kompressor	16,500	60,500
W203 271	14,000	61,000
W203 112	17,000	67,000
W204 M271	14,000	61,000
W205 M274	15,000	43,500
E-CLASS		
W210 M111 E CLASS	11,500	34,000
W210 M112 E CLASS	17,000	56,500
W210 M119 E CLASS	16,000	54,000
213M274 E CLASS	15,500	44,000
W211 271	14,000	48,500
W211 112	17,000	55,000
W212 M271	13,500	47,000
W212 M272	16,500	54,500
M-CLASS		
W163 ML270 (Up to Engine 044707)	15,000	51,000
W163 ML320 M CLASS	17,000	46,500
W164 ML642	17,500	57,500
S-CLASS		
W140 M104 S CLASS	12,000	39,000
W140 M119 S CLASS	12,500	52,000
W140 M120 S CLASS	19,000	48,500
W220 M112 S CLASS	17,000	75,500
W221 M272	16,500	54,500
W221 M273	17,000	55,000
W222 M278	17,500	53,000
CLA	15,000	53,600
GL-CLASS		
GLC 250 4MATIC	15,000	43,500
GLC 250	14,000	37,500
GLC 250 COUPE	15,000	43,500
GLE 350D	17,000	58,000
GLE 400	16,000	47,000
GLE 400 COUPE	16,000	47,000
GLS 350D	17,000	58,000
GLS 400 PETROE	15,500	46,500
GLS 500 PETROE	19,500	52,000
G63 AMG	16,500	52,500

SCOPE OF WORK

MINOR SERVICE FROM 8000KM

- Change the engine oil and engine oil filter
- Inspect the exhaust system.
- Inspect the brake hoses
- Check the engine coolant/antifreeze level, hoses and clamps.
- Inspect engine accessory drive belts. (Replace if necessary)
- Inspect for the presence of water in the fuel filter/ water Separator unit.
- Check brake and Clutch fluid
- Check and correct the tyre pressure
- Check gearbox and axle Oil level.
- Road test the vehicle
- Clean vehicle.
- Give a defect report.

MAJOR SERVICE FROM 24000KM

- Rotate Tyres
- Inspect The CV joints
- Replace the spark plugs. (if necessary, additional cost)
- Adjust the parking brake on the vehicles equipped with four wheel disc brakes.
- Inspect the brake lining; replace if necessary.
- Replace the air Conditioning filter.
- Inspect exhaust system.
- Check power steering fluid level.
- Check door locks operation and lubricate
- Check electrical system
- Check for leaks in major assemblies
- Check trak rods and drag links for play
- Inspect the front suspension, tie rods ends and boot seals for cracks or leaks and all parts for damage, wear, improper looseness or end play; replace if necessary.

Service interval should not exceed 1year

Prices effective from November, 2017

All prices are inclusive of parts, labour and vat And are subject to change without notice.

Mercedes-Benz

The best or nothing.



Monday – Friday: 8.00am - 5.00pm Saturdays: Express Service Only 9.00am - 12.30pm
Closed on Sundays and Public Holidays

Nairobi: 020 7604114 / 0711 057 500 | Email: service.dtdobie@cfao.com

Mombasa: 020 7604111 | Email: service.dtdobie.msa@cfao.com

Nakuru: 020 7604121 | Email: service.dtdobie.nku@cfao.com

Kisumu: 020 7604131